

Inspection Photos
Operator: Simcoe
API: 067-06567
Date: 5/28/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with intermediate wheatgrass, crested wheatgrass, and sand dropseed.



Photos 3. View of the western project area from the southwestern corner facing northward.



Photos 4. View of dense jointed goatgrass within the interim reclamation area.



Photo 5. View of reference area vegetation comprised of irrigated grass field, largely in a grazed vegetative condition.