


Inspection Photos
Operator: Simcoe
API: 067-07845
Date: 5/28/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass and sand dropseed.



Photos 3. View of the western project area from the northwestern corner facing southward. Dense hoary cress infestation observed on the western berm. Approximately 2000 individuals observed. Approximately 10 oxeye daisies observed at the well pad entrance (see inset).



Photos 4. View of reference area, comprised of irrigated grass field.