

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 1 – Spill area. Additional excavation has occurred since last inspection. Soils previously stored on location have been removed.



Photo 2 – Expanded area of investigation. Groundwater with hydrocarbon sheen observed. Impacts remain in situ.

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 3 – Open excavation. Area where free product was previously observed appears to have been partially backfilled. Impacts remain in situ.

Photo 4 – Open excavation. Impacts remain in situ.

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



**Photo 5 – Open excavation. Impacts remain in situ.
Sheen observed on groundwater.**

**Photo 6 – New Spill observed ~75' east of open
excavation.**

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 7 – Dirt being tracked off location onto county road.



Photo 8 – Dirt being tracked off location onto county road.