

Inspection Photos  
Operator: Simcoe  
API: 067-09061  
Date: 5/28/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass and crested wheatgrass.



Photos 3. View of wood debris and other equipment/materials within the southern project area.



Photos 4. View of hoary cress within the western project area. Approximately 100 individuals observed.



Photo 5. View of reference area, comprised of grass field currently grazed with western wheatgrass and forbs such as gumweed and bindweed.



Photos 6. View of closed gate after leaving location.