

Inspection Photos
Operator: Hilcorp
API: 067-07548
Date: 5/28/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass and crested wheatgrass.



Photos 3. View of the western project area from the southwestern corner facing northward.



Photos 4/5. View of debris stored at the well pad entrance and along the southwestern edge of the working area.



Photos 6. View of reference area comprised of open grass field with native and introduced grasses such as smooth brome and crested wheatgrass.