

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2021

Submitted Date:

06/02/2021

Document Number:

699303933

**FIELD INSPECTION FORM**

Loc ID 317868 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448083	TANK BATTERY	AC	10/17/2016		-	SIDNEY STREAR 1,2,3,4,5, 6 BATTERY	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	TB sign is faded and not legible		
Corrective Action:	Comply with Rule 605.e	Date:	07/02/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil identified at various locations through out location.		
Corrective Action:	Comply with Rule 1002..(2).D	Date:	06/07/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	automation		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:	card indicates calibration is not current	
Corrective Action:	Comply with rule 430.d.1, Provide calibration records or calibrate meter within 30 days. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR).	Date: 07/02/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	West Tank may be rusted or pitted, and shows evidence of inadequate repair. making a hissing noise indicating a pin hole.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 07/02/2021

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 448083 Type: TANK API Number: - Status: AC Insp. Status: AC

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 6/2/2021 at approximately 1610 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Sidney Strear 1,2,3,4,5 &amp; 6 Battery</p> <p>at Location #317868 in Weld County Colorado.</p> <p>While there, I observed a tank battery.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1002..(2).D Housekeeping: Stained soil at various points on location, CA date 7-2-2021. See photos 3, 6 &amp; 8.</p> <p>609.b Crude Oil and Condensate Tanks: Tank appears to have a pin hole and is making a hissing noise, CA date 7-2-2021. see attached video.</p> <p>430.d.(1) Calibration: card indicates that calibration on Gas Meter Run is not current, CA date 7-2-2021. See photo 12</p> <p>See attached photos &amp; video.</p> <p>Location: dry, Weather: cloudy.</p> <p>At 1555 hrs I spoke with Manny Silva KPK and let him know about the possible pin hole and leak on the west crude oil tank and he said he would get an operator out to take a look to see about getting it repaired.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	06/02/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303935	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445921">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445921</a>
699303936	pin hole video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445922</a>