

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around WH and braden head riser		
Corrective Action:	Comply with Rule 907.e	Date:	09/29/2020
Type	OTHER		
Comment:	Mechanical issue, WH has a leak around casing and bradenhead riser.		
Corrective Action:	Comply with Rule 605.d	Date:	09/29/2020

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	chainlink topped with barb wire		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	electric panel, meter box and transformer	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 248360 Type: WELL API Number: 123-16158 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/14/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 5/27/2021 at approximately 0950 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up to inspection Doc # 699302543 Anderson 22-32 at API #05-123-16158 in Weld County Colorado. While there, I observed a wellsite, PR at the time of inspection During this inspection the following possible compliance issues were observed and are now delinquent: 605.d Mechanical Issue: WH is leaking around the tubing & appears to have a leak from the Braden head riser , CA date 9-29-2020 see photos 3 & 4. 907.e Stained soil: stained soil around WH and braden head riser CA date 9-29-2020 see photos 5 & 6. See attached photos & video. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	05/27/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402703084	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442618
699303884	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442605
699303885	leak vid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442606