

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2021

Submitted Date:

05/27/2021

Document Number:

700702816

## FIELD INSPECTION FORM

 Loc ID 335858 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

4 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone        | Email                          | Comment                     |
|------------------|--------------|--------------------------------|-----------------------------|
| Dooling, Jessica | 832-624-0810 | jessica.dooling@exxonmobil.com |                             |
| Sutton, Derek    |              | derek_sutton@xtoenergy.com     |                             |
| clark, Erin      | 405-319-3250 | erin.k.clark@exxonmobil.com    | Lead regulatory coordinator |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 281524      | WELL | PR     | 08/01/2017  | GW         | 103-10655 | FEDERAL 2S-95-15-22 | PR          |

**General Comment:****COGCC Inspection Report Summary**

On Wednesday at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at XTO Federal 2S-95-15-22, at Location # 335858 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within BLM stipulations area.

During this inspection the following possible compliance issues were observed:

1. Location shows signs of lack of stabilization/compaction.
  2. Lack of battery signage.
  3. Unmarked ground tank.
  4. Unused equipment (dehy and line heater are disconnected and not in use)
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

| Location   |   |        |                  |
|--|---|--------|------------------|
| <b>Lease Road:</b>                                     |   |        |                  |
| Type   | Access  |        |                  |
| comment:   |   |        |                  |
| Corrective Action                                      |   |        | Date:            |
| Overall Good: <input type="checkbox"/>                 |   |        |                  |
| <b>Signs/Marker:</b>                                   |   |        |                  |
| Type   | CONTAINERS  |        |                  |
| Comment:   |   |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| Type   | BATTERY   |        |                  |
| Comment:   | Lack of battery signage.  |        |                  |
| Corrective Action:                                     | Comply with rule 605.e  |        | Date: 07/02/2021 |
| Type   | WELLHEAD  |        |                  |
| Comment:   |   |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| Type   | TANK LABELS/PLACARDS  |        |                  |
| Comment:   |   |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| Emergency Contact Number:                              |   |        |                  |
| Comment:   | 911   |        |                  |
| Corrective Action:                                     |   |        | Date: _____      |
| <b>Good Housekeeping:</b>                              |   |        |                  |
| Type   | UNUSED EQUIPMENT  |        |                  |
| Comment:   | Unused equipment (dehy and line heater are disconnected and not in use) |        |                  |
| Corrective Action:                                     | remove unused equipment   |        | Date: 08/27/2021 |
| Overall Good: <input type="checkbox"/>                 |   |        |                  |
| <b>Spills:</b>   |   |        |                  |
| Type   | Area  | Volume |                  |
| In Containment: No                                     |   |        |                  |
| Comment:   |   |        |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |                  |
| <b>Equipment:</b>                                      |   |        |                  |
| Type: Dehydrator                                       | # 1   |        | corrective date  |
| Comment:   | see unused equipment  |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| Type: Ancillary equipment                              | # 1   |        |                  |
| Comment:   | 500 gallon methanol tank in metal containment                           |        |                  |
| Corrective Action:                                     |   |        | Date:            |

|                                   |   |  |       |
|-----------------------------------|---|--|-------|
| Type: Deadman # & Marked          | # 6   |  |       |
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Gas Meter Run               | # 2   |  |       |
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Horizontal Heated Separator | # 1   |  |       |
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Other                       | # 1   |  |       |
| Comment:                          | well head not on plunger lift                 |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Bradenhead                  | # 1   |  |       |
| Comment:                          | Braden heads have a PSI gauge for monitoring. |  |       |
| Corrective Action:                |   |  | Date: |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type      | Tank ID | SE GPS           |
|--------------------|--|----------|-----------|---------|------------------|
|                    | 1  | 100 BBLs | STEEL AST |         |                  |
| Comment:           | 100 bbl open top ground tank is open to Atmosphere is missing labeling |          |           |         |                  |
| Corrective Action: | install proper signage   |          |           |         | Date: 06/04/2021 |

Paint

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 2 | 300 BBLs | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         |        |
|                    |   |          |           |         | Date:  |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

Berms

|       |          |                     |                     |             |  |
|-------|----------|---------------------|---------------------|-------------|--|
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
| Metal | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |  |

|                    |  |  |  |       |  |
|--------------------|--|--|--|-------|--|
| Comment:           |  |  |  |       |  |
| Corrective Action: |  |  |  | Date: |  |

|                |   |          |           |         |        |
|----------------|---|----------|-----------|---------|--------|
| Contents       | # | Capacity | Type      | Tank ID | SE GPS |
| PRODUCED WATER | 2 | 500 BBLs | STEEL AST |         | ,      |

|                    |  |  |  |       |  |
|--------------------|--|--|--|-------|--|
| Comment:           |  |  |  |       |  |
| Corrective Action: |  |  |  | Date: |  |

**Paint**

|                  |          |  |  |  |  |
|------------------|----------|--|--|--|--|
| Condition        | Adequate |  |  |  |  |
| Other (Content)  |          |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |
| Other (Type)     |          |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |  |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |  |
| Comment:           |          |                     |                     |             |  |
| Corrective Action: |          |                     |                     | Date:       |  |

**Venting:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Yes/No             | YES  |  |       |
| Comment:           | 100 bbl open top ground tank is open to Atmosphere |  |       |
| Corrective Action: |  |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

Facility ID: 281524 Type: WELL API Number: 103-10655 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Culverts                |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       | Fail            |                         |                       |               |                          |         |

Comment: All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within BLM stipulations area.  
1. Location shows signs of lack of stabilization/compaction.

Corrective Action: Install or repair required BMPs

Date: 07/02/2021

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402703405    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442932">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442932</a> |
| 700702821    | photo log            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442927">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442927</a> |