



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: electric

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 241106 Type: WELL API Number: 123-08894 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 11/12/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were warm, overcast, windy, recent rain.	medinaj	06/03/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502837	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5446784">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5446784</a>