

Inspection Photos
H. Huett Consolidation Release
Spill ID 478005 (AC)



Photo 1 –Fencing down around open excavation.



Photo 2 – Spill excavation. Groundwater with hydrocarbon sheen observed in open excavation.

Inspection Photos
H. Huett Consolidation Release
Spill ID 478005 (AC)



Photo 3 – Spill excavation. Hydrocarbons observed on groundwater in open excavation.



Photo 4 – Exposed flowline in open excavation.

Inspection Photos
H. Huett Consolidation Release
Spill ID 478005 (AC)



Photo 5 – Spill excavation. Hydrocarbons sheen observed on groundwater in open excavation.



Photo 6 – Spill excavation.