

Well Name : LTJ Partnership (OWP) 13-28

API # : 123-11243



Photo 1: Storm water pooling at the top of the rise where P&A well site is located.



Photo 2: Access road entry point onto well site.

Well Name : LTJ Partnership (OWP) 13-28

API # : 123-11243



Photo 3: View from entry point looking downslope towards CR.



Photo 4: Additional view looking down slope towards CR showing water flow on access road.

Well Name : LTJ Partnership (OWP) 13-28

API # : 123-11243



Photo 5: Additional view looking down slope towards CR showing water flow on access road. Standing water visible.



Photo 6: Looking upslope towards well site.



Well Name : LTJ Partnership (OWP) 13-28

API # : 123-11243



Photo 7: Same position looking down slope towards CR.



Photo 8: Additional view looking upslope past previous photo of water standing in ruts.

Well Name : LTJ Partnership (OWP) 13-28

API # : 123-11243



Photo 9: View with CR visible at end of access road.



Photo 10: View looking upslope at edge of CR.

Well Name : LTJ Partnership (OWP) 13-28

API # : 123-11243



Photo 11: View at CR and access road intersection.



Photo 12: View looking upslope at CR and access road intersection.



Well Name : LTJ Partnership (OWP) 13-28

API # : 123-11243



Photo 13: View below culvert looking upslope at bar ditch erosion.



Photo 14: View of sediment plumb out of culvert into adjacent field.