

Inspection Photos

API: 073-06209

Operator: CITATION OIL & GAS CORP

Inspection Date: 6/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



Photo 1. Facing southwest toward the access road from the County Road has not been reclaimed. There is two access points into the abandoned facility.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



Photo 2. Facing northwest toward the access road from the County Road has not been reclaimed. There is two access points into the abandoned facility.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



06.02.2021

Photo 3. Facing northwest at the abandoned tank battery facility. The facility area consists predominately of undesirable weeds which has to be controlled. The facility has not re-established a desirable vegetation cover.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



Photo 4. Facing north at the abandoned tank battery facility. The facility area consists predominately of undesirable weeds which has to be controlled. The facility has not re-established a desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



Photo 5. Facing northwest along the former access road. The majority of the road has re-established vegetation. The area where the road turns has bare areas that will needed addition reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



Photo 6. Facing northwest at the location. The perimeter of the location is fenced and maintenance is needed on the fence.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



Photo 7. Facing northwest at the location. The location consists predominately of undesirable weeds which has to be controlled. The location has not re-established a desirable vegetation cover.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



Photo 8. View of ground cover shows undesirable weeds (Kochia sp.) which was observed throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021

Inspection Photos



Photo 9. Facing west toward the undisturbed surrounding rangeland which consists of Blue grama, Sand dropseed among other native vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 6/2/2021