

Inspection Photos

Operator: Catamount Energy
API: 067-09380
Date: 6/3/2021



Photo 1. View of project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass, fourwing saltbush, crested wheatgrass, smooth brome, and rubber rabbitbrush.



Photos 3. View of the northern project area from the northeastern corner facing westward.



Photos 4. View of Russian knapweeds within the eastern project area. Approximately 1000 individuals observed.



Photos 5. View of reference area comprised of big sagebrush and black sagebrush shrubland with mosaic of western wheatgrass, squirreltail, and phlox.