

Inspection Photos
Operator: Catamount Energy
API: 067-08184
Date: 6/3/2021



Photo 1. View of project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass, crested wheatgrass, smooth brome, and rubber rabbitbrush.



Photos 3. View of the southern project area from the southeastern corner facing westward.



Photos 4. View of Russian knapweeds within the eastern project area. Approximately 1000 individuals observed.



Photos 5. View of reference area comprised of big sagebrush and black sagebrush shrubland with mosaic of western wheatgrass, squirreltail, and phlox.