

Inspection Photos

API: 073-06310

Operator: NIGHTHAWK PRODUCTION LLC

Inspection Date: 6/2/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06310 | Date: 6/2/2021

Inspection Photos




Photo 1. Facing east along the former access road. The location is shown at red arrow.



Inspection Photos



Photo 2. Facing northeast at the location. There is undesirable weeds (Kochia) growing throughout this southwest portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06310 | Date: 6/2/2021

Inspection Photos



Photo 3. Facing north at the center of the location. The vegetation has not adequately established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06310 | Date: 6/2/2021

Inspection Photos



Photo 4. Facing west at the center of the location. The vegetation has not adequately established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06310 | Date: 6/2/2021

Inspection Photos



Photo 5. Facing south at the center of the location. The vegetation has not adequately established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06310 | Date: 6/2/2021

Inspection Photos



Photo 6. Facing east at the center of the location. The vegetation has not adequately established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06310 | Date: 6/2/2021

Inspection Photos



Photo 7. Facing southeast toward the undisturbed surrounding area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06310 | Date: 6/2/2021