

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2021

Submitted Date:

06/02/2021

Document Number:

699303933

FIELD INSPECTION FORM

Loc ID 317868 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gintautas, Peter		peter.gintautas@state.co.us	
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections
Pesika, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448083	TANK BATTERY	AC	10/17/2016		-	SIDNEY STREAR 1,2,3,4,5, 6 BATTERY	AC

General Comment:

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	TB sign is faded and not legible		
Corrective Action:	Comply with Rule 605.e		Date: 07/02/2021

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil identified at various locations through out location.		
Corrective Action:	Comply with Rule 1002..(2).D		Date: 06/07/2021

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:			Date:

Equipment:

Type			corrective date
Ancillary equipment	# 2		
Comment:	automation		
Corrective Action:			Date:
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1	
Comment:	card indicates calibration is not current	
Corrective Action:	Comply with rule 430.d.1, Provide calibration records or calibrate meter within 30 days. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR).	Date: 07/02/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	50 bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tank			
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	West Tank may be rusted or pitted, and shows evidence of inadequate repair. making a hissing noise indicating a pin hole.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 07/02/2021

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			

Flaring:

Type			
------	--	--	--

Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 448083 Type: TANK API Number: - Status: AC Insp. Status: AC**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 6/2/2021 at approximately 1610 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: center;">Sidney Strear 1,2,3,4,5 & 6 Battery</p> <p>at Location #317868 in Weld County Colorado. While there, I observed a tank battery. During this inspection the following possible compliance issues were observed: 1002.(2).D Housekeeping: Stained soil at various points onlocation, CA date 7-2-2021. See photos 3, 6 & 8. 609.b Crude Oil and Condensate Tanks: Tank appears to have a pin hole and is making a hissing noise, CA date 7-2-2021. see attached video. 430.d.(1) Calibration: card indicates that calibration on Gas Meter Run is not current, CA date 7-2-2021. See photo 12 See attached photos & video. Location: dry, Weather: cloudy. At 1555 hrs I spoke with Manny Silva KPK and let him know about the possible pin hole and leak on the west crude oil tank and he said he would get an operator out to take a look to see about getting it repaired. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	06/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402706953	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445924
699303935	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445921
699303936	pin hole video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445922