

Inspection Photos
Paul Heinze #1 Flowline & Paul Heinze #1 Flowline (No. 2)
Spill ID 479232 (AC) & Spill ID 480128 (AC)



Photo 1 – Spill area. Excavation in process at the time of the inspection.

Photo 2 – Open excavation. Excavation appears to have been partially backfilled.

Inspection Photos
Paul Heinze #1 Flowline & Paul Heinze #1 Flowline (No. 2)
Spill ID 479232 (AC) & Spill ID 480128 (AC)



Photo 3 – Open excavation. Area where free product was previously observed appears to have been partially backfilled.

Photo 4 – Open excavation. Impacts remain in situ. Excavation appears to have been partially backfilled.

Inspection Photos
Paul Heinze #1 Flowline & Paul Heinze #1 Flowline (No. 2)
Spill ID 479232 (AC) & Spill ID 480128 (AC)



Photo 5 – Vehicle tracking BMPs have been installed and dirt previously carried of location has been removed/cleaned.

Photo 6 – New Spill (spill ID 480128). Surface area has been scraped. Impacts remain in situ and visible on the surface.