



- Photo 1 – Wellhead view south, no sign at wellhead



- Photo 2 – Non E&P waste impacted soil at pumping unit motor, view west





- Photo 3 – Non E&P waste impacted soil at pumping unit motor





- Photo 4 – Non E&P waste impacted soil at pumping unit motor





- Photo 5 – Non E&P waste impacted soil at pumping unit motor





- Photo 6 – Wellhead view north-northeast



- Photo 7 –





- Photo 8 –





- Photo 9 –





- Photo 10 – Erosion rilling indicates secondary containment rainwater drained toward depression at the base of the oil skim tank see next photo





- Photo 11 –





- Photo 12 –





- Photo 13 –





- Photo 14 –





- Photo 15 –





- Photo 16 –