

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2021

Submitted Date:

06/10/2021

Document Number:

688000543

**FIELD INSPECTION FORM**Loc ID 319921 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Canfield, Chris		chris.canfield@state.co.us	
Allison, Rick		rick.allison@state.co.us	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201895	WELL	PR	02/01/2021	OW	001-07299	GREEN 1	EI

**General Comment:**

Environmental inspection related to Complaint #200449737. Small amount of non E&P impacted soil associated with the pumping unit motor. No signs of active fluid leakage at the time of inspection.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: No sign at wellhead.Corrective Action: Install sign at wellhead.Date: 06/25/2021**Good Housekeeping:**

Type	OTHER		
Comment:	Non E&P waste at pumping unit motor.		
Corrective Action:	Control the source of the leaking fluid, clean up impacted soils and properly dispose per Rule 906.		Date: <u>06/18/2021</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Prime Mover	#		corrective date
Comment:	Motor leaking non E&P Waste onto the ground.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>06/25/2021</u>

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	Erosion rills and a depression on the west side of the oil skim tank indicate rapid drainage of stormwater due to a preferential pathway. See attached photos 10 and 11.					
Corrective Action:	Investigate the source of the rapid drainage and repair as necessary to ensure compliance with Rule 603.o.(4).				Date:	<u>06/25/2021</u>

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 201895 Type: WELL API Number: 001-07299 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000544	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5452684">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5452684</a>