

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2021

Submitted Date:

06/04/2021

Document Number:

690201603**FIELD INSPECTION FORM**Loc ID 429618 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10630Name of Operator: ALTA MESA SERVICES LPAddress: 15021 KATY FREEWAY SUITE 400City: HOUSTON State: TX Zip: 77094**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
JAMESON MAX		mjameson@altamesa.net	
KASSAB, DIANE		DKassab@high-mesa.com	
KASSAB, DIANE		dkassab@altamesa.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429619	WELL	PA	12/02/2017	OW	055-06309	Freeman 3-24	RI

**General Comment:**

This is a follow up of the previous reclamation inspections; document number 673504379, 673504439, 689900032, 689900273, 674902271, 689900323, 689900885, 689901093, 689901444, 690200335, 690200773. Corrective action of the previous inspections have not been performed. See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

## 1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Interim reclamation was not performed prior to plugging the well. A form 6 Well Abandonment Report was submitted indicating the well was plugged and abandoned on 12/2/2017. The total area of the location was 4.42 acres excluding the new unpermitted disturbance. The 2A specifies the size of the location after Interim Reclamation must be 1.2 acres. The operator was directed to request delayed interim reclamation following the NTO: Interim Reclamation Procedures for Delayed Operations. A complete delayed interim reclamation request was not submitted. The location has been out of compliance for Interim reclamation since 2014.

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: The well was plugged and abandoned on 12/2/2017.

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed **Fail**

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded **Fail**Contoured **Fail**Culverts removed **Fail**Gravel removed **Fail**Location and associated production facilities reclaimed **Fail**Locations, facilities, roads, recontoured **Fail**Compaction alleviation **Fail**Dust and erosion control **Fail**Non cropland: Revegetated 80% **Fail**

Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail**

Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:	The access road and eastern portion of the location have not been recontoured and reclaimed. The western and northern portion of the location which was reclaimed does not have sufficient desirable vegetation establishment and seeding has failed. There are undesirable and noxious weeds throughout the location. There are dead trees that remain and no replacement trees were planted. Reseeding and weed control have not been performed and there is weed debris throughout the location. Corrective actions of the previous inspections have not been performed. Corrective action needs to be performed immediately.	Date _____
Corrective Action:	<p>Comply with 1004 Rules.</p> <p>Reclaim the access road and eastern portion of the location.</p> <p>Remove the cattle guard and culvert from the access road.</p> <p>Monitor and control weeds and remove weed debris.</p> <p>Remove remaining dead trees and replant new trees.</p> <p>Reseed the location to establish a uniform vegetation cover reflective of the reference area.</p>	
Overall Final Reclamation <b>Fail</b> Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/>		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402708677	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447581">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447581</a>
690201604	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447580">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447580</a>