

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222; Spill ID 479267



Photo 1 Well Sign




Photo 2 Flowline exposed in excavation, looking north



Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222; Spill ID 479267



Photo 3 Eastern side of excavation looking north



Photo 4 Western side of excavation, looking east

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222; Spill ID 479267



Photo 5 Northwestern side of excavation, looking southeast



Photo 6 Stockpile area for oily waste pending disposal



Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222; Spill ID 479267



Photo 7 Clean overburden stockpile

