

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484




Photo 1 Tank Battery Sign




Photo 2 Fence unsecure at east end tank battery entrance

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 3 Eastern excavation, from northeast corner looking southwest



Photo 4 Eastern excavation, from northeast corner looking south

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 5 Eastern excavation, from south side looking northwest



Photo 6 Flowline or dumpline piping in western wall of eastern excavation

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



COGCC
40.11657, -104.9683, 4868.2ft
06/10/2021 09:45:03

Photo 7 Flowlines, piping, produced water vessel and emission control devices stage and out of use.



COGCC
40.11666, -104.96836, 4869.4ft
06/10/2021 09:45:18

Photo 8 Western excavation looking west

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 9 Separator staged and out of use.

