

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #4050 from entrance to location.



Photo #4051 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #4052 Location lacks stabilization.



Photo #4053 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #4054 No form of tracking BMP located at entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources