

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2021

Submitted Date:

06/11/2021

Document Number:

693700824

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 ALLISON, RICK 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10718

Name of Operator: TAPROOT ROCKIES MIDSTREAM LLC

Address: 555 17TH STREET SUITE 800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dale Hunt		dhunt@taprootep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467382	Produced Water Transfer System	AC	09/10/2019		-	EWS#1 001	EI

General Comment:

COGCC Environmental Inspection of Produced Water Spill

Environmental**Spill/Remediation:**

Comment: Operator reported produced water spill on Form 19 Doc 402711705. All standing water has been removed and failed section of water line repaired and backfilled at the time of inspection. Operator will submit a remediation information including volume excavated and disposed, confirmation soil sample results, site map showing excavation and sample locations, root cause and corrective actions on a Form 19 Supplemental Report.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____