

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2021

Submitted Date:

06/11/2021

Document Number:

693505217

**FIELD INSPECTION FORM**Loc ID 335770 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240586	WELL	PR	02/01/2020	OW	123-08374	WAGNER 1-A	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:	Date: _____		

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Flowline and Crude Oil Transfer Line Statuses. (marking and LOTO)		
Corrective Action:	Comply with rule 1101 a		Date: 07/11/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel. Electric breaker is in the off position.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Inspected Facilities**Facility ID: 240586 Type: WELL API Number: 123-08374 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI. At time of inspection flow line vavles are closed.Corrective Action:  Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday July 11 2021 at approximately 11:42AM, I, Inspector Randy Silver, Conducted an on-site follow up inspection per doc#688401737.</p> <p>Location: Wagner #1-A</p> <p>Operator: KP Kauffman</p> <p>API#: 123-08374</p> <p>County: Weld</p> <p>While there, I observed a SI well site.</p> <p>During this inspection the following possible compliance issues were observed.</p> <p>Flowline transfer lines: Rule 1101 a Corrective action date of 7-11-21</p> <p>Weather conditions: Clear and hot.</p> <p>This is a follow up inspection, at time of inspection open trench with electric and gas line has not been addressed since last inspection Doc#688401737 3-2-19 witch inspector commented on open excavation. KPK has not addressed issue.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	06/11/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505218	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453396">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453396</a>