

# Inspection Photos

API: 061-06233

Operator: OXY USA INC

Inspection Date: 6/9/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06233 | Date: 6/9/2021

## Inspection Photos



**Photo 1.** Facing northwest toward the location. There is a pipeline riser at the location. No crop was planted at the location this year to evaluate crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06233 | Date: 6/9/2021

## Inspection Photos



**Photo 2.** View of pipeline riser at the location. No sign identifying the riser is present.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06233 | Date: 6/9/2021