

Inspection Photos

API: 017-07524

Operator: P O & G OPERATING LLC

Inspection Date: 6/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021

Inspection Photos



Photo 1. Facing toward the abandoned facility battery site. This area has not ben reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021

Inspection Photos



Photo 2. There are areas that are bare of vegetation growth and undesirable weeds throughout the disturbed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021

Inspection Photos



Photo 3. View of undesirable and noxious weeds (Kochia sp., Field bindweed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021

Inspection Photos



Photo 4. Facing north at the location. All disturbed areas of the location need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021

Inspection Photos



Photo 5. Facing east at the well site located in a crop field that has not been planted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021

Inspection Photos



Photo 6. Facing northeast at the location. All disturbed areas of the location need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021

Inspection Photos



Photo 7. There is an abandoned pipe riser 1200' northwest of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021

Inspection Photos



Photo 8. Facing north toward the adjacent surrounding reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07524 | Date: 6/9/2021