

Inspection Photos

API: 061-06296

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/9/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/9/2021

Inspection Photos



Photo 2. The fence is not maintained around the tank battery to prevent livestock entry. Cattle tracks are shown along the berm.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/9/2021

Inspection Photos



Photo 3. There is oil stained soil around the tank. The stained soil needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/9/2021

Inspection Photos



Photo 4. The fence is not maintained around the tank battery to prevent livestock entry. Cattle tracks are shown along the berm.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/9/2021

Inspection Photos

Jun 10, 2021 at 8:44:17 AM
+38.626487,-102.422849



Photo 5. Facing south toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/9/2021