

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2021

Submitted Date:

06/14/2021

Document Number:

696303349**FIELD INSPECTION FORM**Loc ID 427041 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10503Name of Operator: RED HAWK PETROLEUM LLCAddress: 575 N DAIRY ASHFORD STE 201City: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone | Email                   | Comment                         |
|----------------|-------|-------------------------|---------------------------------|
| Shepard, DeAnn |       | dshepard@pedevco.com    | <a href="#">All Inspections</a> |
| Boyd, William  |       | wboyd@pedevco.com       | <a href="#">All Inspections</a> |
| Kraich, Adam   |       | adam.kraich@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 427019      | WELL | PR     | 08/01/2018  | OW         | 123-34825 | Buchner 1-2H  | PR          |

**General Comment:**[Follow-Up Inspection to FIR 696303126 dated 04.23.2021 and FIRR 402668876 dated 04.23.2021](#)

**Location**Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             | Adequate - Updated Emergency Contact Info has been posted  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             | Middle Crude Oil Tank - Content and Capacity Labels are fading - STILL NOT addressed. See photos |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.h.  | Date: | 05/14/2021 |
| Type                 | CONTAINERS   |       |            |
| Comment:             | Adequate   |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | BATTERY  |       |            |
| Comment:             | Adequate   |       |            |
| Corrective Action:   |  | Date: |            |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | OTHER   |       |  |
| Comment:           | Stained Soil has been cleaned up for now. Please continue to perform routine checks on this on-going issue. |       |  |
| Corrective Action: |   | Date: |  |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                               |     |       |                 |
|-------------------------------|-----|-------|-----------------|
|                               |     |       | corrective date |
| Type: Vertical Separator      | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Pump Jack               | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Vertical Heater Treater | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Flare                   | # 1 |       |                 |

|                               |                                  |       |  |
|-------------------------------|----------------------------------|-------|--|
| Comment:                      |                                  | Date: |  |
| Corrective Action:            |                                  | Date: |  |
| Type: Bradenhead              | # 1                              |       |  |
| Comment:                      | Appears to be plumbed to surface | Date: |  |
| Corrective Action:            |                                  | Date: |  |
| Type: Gas Meter Run           | # 1                              |       |  |
| Comment:                      |                                  | Date: |  |
| Corrective Action:            |                                  | Date: |  |
| Type: Emission Control Device | # 1                              |       |  |
| Comment:                      |                                  | Date: |  |
| Corrective Action:            |                                  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 400 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 3 | 400 BBLS | STEEL AST |         | 40.603210,-104.067003 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |             |       |
|--------------------|-------------|-------|
| Type               | Field Flare |       |
| Comment:           |             |       |
| Corrective Action: |             | Date: |

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 427019 | Type: | WELL | API Number: | 123-34825 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |       |      |             |           |         |    |               |    |
| Comment:             | PR     |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><a href="#">COGCC Inspection Report Summary</a></p> <p>On Thursday 06/14/2021 at approximately 13:58, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Red Hawk Petroleum LLC , Buchner 1-2H, Location #427041 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed</p> <p>Middle Crude Oil Tank - Content and Capacity. Install sign to comply with Rule 605.h. Corrective Action Date 05.14.2021 *Issue STILL NOT addressed</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p> | petrie | 06/14/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696303350    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5455450">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5455450</a> |