

Inspection Photos

API: 071-08776

Operator: XTO ENERGY INC

Inspection Date: 6/15/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 1. Facing north toward the access road. Gravel has been spread along the road for stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 2. There is sediment accumulation along this rip/rap outlet which needs maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 3. Facing northwest along the access road. This portion of the road appears stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 4. Sediment has accumulated on some of the check dams which need maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 5. The access road continues to the right at this junction in the road. Gravel ends at this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 6. Facing northwest. There is erosion beginning to occur which needs maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 7. Facing northwest along the road. Culverts are installed along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 8. Facing west near the location. There are noxious weeds in the area circled which need to be controlled before further infestation occurs. (Canada thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 9. Facing northwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 10. Facing northwest toward the location. Additional seeding along the right side of the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 11. There are noxious weeds in the area circled which need to be controlled before further infestation occurs. (Canada thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 12. Facing south along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021

Inspection Photos



Photo 13. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 6/15/2021