

Inspection Photos

API: 071-09381

Operator: XTO ENERGY INC

Inspection Date: 6/15/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 1. Facing north toward the access road. There is some sediment beginning to fill into the cattle guard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 2. Stormwater is causing erosion at the beginning steep grade of the road. Storm water should be diverted off the road to prevent erosion (berm, water bar).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 3. Facing back along the access road. Stormwater should be diverted off the road to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 4. Facing northwest along the access road which remains per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 5. Facing northwest toward the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 6. Facing northwest along the access road. There is field bind weed along this area which should be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 7. There are noxious weeds in the area circled which need to be controlled before further infestation occurs. (Canada thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 8. There are straw bales around the perimeter that have degraded. The bales should be removed or replaced if needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 9. Facing southwest along the reclaimed location. This area could use some maintenance such as hand seeding to help establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 10. Facing southwest along the reclaimed location. There is a diversion berm along this area which could use some maintenance and hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 11. Facing northeast along the top portion of the reclaimed location. Vegetation is establishing well within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 12. There is an area of erosion at the west side of the location which will need to be repaired and stabilized.



Inspection Photos



Photo 13. There are straw bales around the perimeter that have degraded. The bales should be removed or replaced if needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 14. Facing east along the bottom of the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 15. Facing northeast toward the reclaimed location. There is desirable vegetation progressing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 16. Facing northwest toward the reclaimed location. There is desirable vegetation progressing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 17. This area could use some maintenance such as hand seeding to help establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021

Inspection Photos



Photo 18. Facing northwest at the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09381 | Date: 6/15/2021