

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2021

Submitted Date:

06/15/2021

Document Number:

700702854

FIELD INSPECTION FORM

Loc ID 335884 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORT WORTH State: TX Zip: 76102

Findings:

- 18 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|--------------------------------|---|
| Dooling, Jessica | 832-624-0810 | jessica.dooling@exxonmobil.com | |
| clark, Erin | 405-319-3250 | erin.k.clark@exxonmobil.com | Lead regulatory coordinator |
| Sutton, Derek | | derek_sutton@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 285712 | WELL | PR | 06/08/2012 | GW | 103-10818 | PICEANCE CREEK UNIT 296-7A5 | PR |
| 285713 | WELL | PR | 01/01/2020 | GW | 103-10819 | PICEANCE CREEK UNIT 296-7A4 | PR |
| 285714 | WELL | PR | 02/01/2021 | GW | 103-10820 | PICEANCE CREEK UNIT 296-7A3 | PR |
| 285715 | WELL | PR | 03/01/2021 | GW | 103-10821 | PICEANCE CREEK UNIT 296-7A2 | PR |
| 285716 | WELL | PR | 02/01/2021 | GW | 103-10822 | PICEANCE CREEK UNIT 296-7A1 | PR |
| 285717 | WELL | PR | 01/01/2021 | GW | 103-10823 | PICEANCE CREEK UNIT 296-7A9 | PR |
| 285718 | WELL | PR | 06/01/2019 | GW | 103-10824 | PICEANCE CREEK UNIT 296-7A8 | PR |
| 285719 | WELL | PR | 01/17/2009 | GW | 103-10825 | PICEANCE CREEK UNIT 296-7A7 | PR |
| 285720 | WELL | PR | 12/01/2020 | GW | 103-10826 | PICEANCE CREEK UNIT 296-7A6 | PR |

General Comment:

COGCC Inspection Report Summary

On Tuesday 6/15/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a Follow up inspection at XTO 296-7A, at Location # 335884 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area, BLM stipulations area and CDPHE Reg. 42 area.

C/A's from previous inspection document # 701500276 have been satisfied.

During this inspection the following possible compliance issues were observed:

1. Lack of battery signage
2. Random debris around location
3. Stained soil at well head

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

| Location | | | |
|--|--|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Lack of battery signage | | |
| Corrective Action: | Comply with rule 605.e | | Date: 07/15/2021 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Random debris around location | | |
| Corrective Action: | remove all debris | | Date: 06/25/2021 |
| Type | OTHER | | |
| Comment: | Stained soil at well head | | |
| Corrective Action: | remove all stained material | | Date: 06/25/2021 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Ancillary equipment | # 6 | | corrective date |
| Comment: | chemical tanks at manifold some are in metal containments and some have plastic containments | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|---|--|-------|
| Type: Plunger Lift | # 9 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 9 | | |
| Comment: | Braden heads have manual gauge monitoring | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 285712 | Type: | WELL | API Number: | 103-10818 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285713 | Type: | WELL | API Number: | 103-10819 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285714 | Type: | WELL | API Number: | 103-10820 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285715 | Type: | WELL | API Number: | 103-10821 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285716 | Type: | WELL | API Number: | 103-10822 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285717 | Type: | WELL | API Number: | 103-10823 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285718 | Type: | WELL | API Number: | 103-10824 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285719 | Type: | WELL | API Number: | 103-10825 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |

Facility ID: 285720 Type: WELL API Number: 103-10826 Status: PR Insp. Status: PR

Producing Well

Comment: [producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Culverts | | | | |
| | | Ditches | | | | |

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area, BLM stipulations area and CDPHE Reg. 42 area.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
| | 284684 | 200090057 | |
| | 284684 | 200090057 | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 700702860 | photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5456468 |