

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2021

Submitted Date:

06/15/2021

Document Number:

700702855

**FIELD INSPECTION FORM**Loc ID 315259 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	832-624-0810	jessica.dooling@exxonmobil.com	
clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	Lead regulatory coordinator
Sutton, Derek		derek_sutton@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230511	WELL	PR	07/10/1978	GW	103-08178	U S A-PICEANCE CREEK F81-18G	PR

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 6/15/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at XTO F81-18G, at Location # 315259 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area, BLM stipulations area and CDPHE Reg. 42 area.

During this inspection the following possible compliance issues were observed:

1. Lack of battery signage
  2. Location shows signs of lack of stabilization/compaction
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e	Date:	07/15/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Braden heads have a manual gauge monitoring		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	OTHER	STEEL AST		,	
Comment:	210 bbl tank					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	230511	Type:	WELL	API Number:	103-08178	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
		Culverts				
Berms						
		Ditches				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area, BLM stipulations area and CDPHE Reg. 42 area.  
1. Location shows signs of lack of stabilization/compaction

Corrective Action: Install or repair required BMPs

Date: 07/15/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702861	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5456469">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5456469</a>