

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2021

Submitted Date:

06/10/2021

Document Number:

689501288

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Canfield, Chris		chris.canfield@state.co.us	
,		mknop@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479232	SPILL OR RELEASE	AC			-	Paul Heinze #1 Flowline	EI
480128	SPILL OR RELEASE	AC			-	Paul Heinze #1 Flowline (No. 2)	EI

**General Comment:**

This is a follow-up inspection to Doc#691201499; environmental inspection of Spill ID 479232. Any corrective actions from previous inspections that have not been addressed are still applicable.

[Photos attached to document site conditions.](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash was not observed. However due to work being conducted entire work area was not inspected.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Vehicle tracking BMPs have been installed since last inspection and dirt tracked onto county road has been removed.		
Corrective Action:			Date:

Overall Good:

**Spills:**

Type	Area	Volume			
Crude Oil	Flow Line	>= 5 bbls			
Comment:	From 19 has been submitted for spill discovered in inspection #691201499 (Form 19 Doc#402707700 Spill ID 480128). Surface soils have been scraped but impacts remain in situ/visible on the surface.				
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. In accordance with Rule 912.a.(6) No later than 90 days after a Spill or Release is discovered Operator will submit a Form 19 Supplemental requesting closure pursuant to Rule 913.h or a Form 27 Workplan with a timeline for investigation and closure of this release.			Date:	08/31/2021

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Fencing was removed so that work could be completed.		
Corrective Action:			Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 479232 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Facility ID: 480128 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill excavation is open and work was in progress on the location at the time of inspection. The excavation had been partially backfilled and soil had been pushed over groundwater so inspectors could not determine if free product had been removed. Soil impacts in situ. Initial Form 19 (Doc# 402577378) documents a spill discovery date of 1/17/2021

Corrective Action: In accordance with Rule 912.a.(6) No later than 90 days after a Spill or Release is discovered Operator will submit a Form 19 Supplemental requesting closure pursuant to Rule 913.h and a Form 27 Workplan with a timeline for investigation and closure of this release. Operator will provide notice to COGCC EPS Kari Brown(kari.l.brown@state.co.us) at least 48 hours prior to backfill or any sampling events performed on location. Note that samples collected must be analyzed for Table 915-1 parameters Date: 04/02/2021

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)	
Comment	Oily soils previously stored on location had been removed and additional soils were being stockpiled at the time of inspection.				
Corrective Action	Provide disposal manifests and gate tickets for removed soil via Supplemental Form 19.				Date: <u>06/15/2021</u>

**Spill/Remediation:**

Comment: Free product was observed in contact with groundwater between 2/22/2021 and 5/14/2021. At time of inspection soil had been placed over water table and inspectors were unable to confirm if it had been removed.

Corrective Action: Provide disposal manifests documenting cleanup of removed free product via Supplemental Form 19. Date: 06/15/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402714388	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5451969">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5451969</a>
689501289	Field Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5451968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5451968</a>