

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/10/2021

Submitted Date:

06/10/2021

Document Number:

699303982

**FIELD INSPECTION FORM**
 Loc ID 456589 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
| ,            |       | COGCCinspections@anadarko.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 456573      | WELL | PR     | 08/19/2019  | OW         | 123-47567 | BAJA BERG 35-5HZ | PR          |
| 456578      | WELL | PR     | 08/12/2019  | OW         | 123-47569 | BAJA BERG 35-9HZ | PR          |
| 456583      | WELL | PR     | 08/17/2019  | OW         | 123-47573 | BAJA BERG 35-4HZ | PR          |
| 456585      | WELL | PR     | 08/13/2019  | OW         | 123-47574 | BAJA BERG 35-6HZ | PR          |
| 456588      | WELL | DG     | 09/15/2018  | OW         | 123-47577 | BAJA BERG 35-7HZ | ND          |
| 456592      | WELL | PR     | 08/16/2019  | OW         | 123-47580 | BAJA BERG 35-1HZ | PR          |
| 456594      | WELL | PR     | 08/17/2019  | OW         | 123-47582 | BAJA BERG 35-3HZ | PR          |
| 456597      | WELL | PR     | 08/12/2019  | OW         | 123-47585 | BAJA BERG 35-8HZ | PR          |
| 456599      | WELL | PR     | 08/15/2019  | OW         | 123-47586 | BAJA BERG 35-2HZ | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                                  |       |  |
|--------------------|----------------------------------|-------|--|
| <b>Fencing/:</b>   |                                  |       |  |
| Type               | WELLHEAD                         |       |  |
| Comment:           | Ag panel                         |       |  |
| Corrective Action: |                                  | Date: |  |
| Type               | TANK BATTERY                     |       |  |
| Comment:           | Chain link topped with barb wire |       |  |
| Corrective Action: |                                  | Date: |  |

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Plunger Lift        | # 8   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Compressor          | # 2   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 20  |       |                 |
| Comment:                  | Electric panels, transformers, automation and corrosion inhibitor |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Bird Protectors     | # 9   |       |                 |

|                                   |     |   |       |
|-----------------------------------|-----|---|-------|
| Comment:                          |     |   |       |
| Corrective Action:                |     |   | Date: |
| Type: Emission Control Device     | # 1 |   |       |
| Comment:                          |     |   |       |
| Corrective Action:                |     |   | Date: |
| Type: Gas Meter Run               | # 1 |   |       |
| Comment:                          |     | Gas meter calibration record not legible or conspicuously displayed at meter.   |       |
| Corrective Action:                |     | Provide calibration records or calibrate meter as required by Rule 430 within 30 days. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR). |       |
|                                   |     | Date: 07/10/2021  |       |
| Type: Horizontal Heated Separator | # 8 |   |       |
| Comment:                          |     |   |       |
| Corrective Action:                |     |   | Date: |
| Type: Bradenhead                  | # 8 |   |       |
| Comment:                          |     | appear to be plumbed to surface   |       |
| Corrective Action:                |     |   | Date: |
| Type: LACT                        | # 2 |   |       |
| Comment:                          |     |   |       |
| Corrective Action:                |     |   | Date: |
| Type: FWKO                        | # 2 |   |       |
| Comment:                          |     |   |       |
| Corrective Action:                |     |   | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | OTHER    | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                          |          |
|--------------------------|----------|
| Condition                | Adequate |
| Other (Content)          |          |
| Other (Capacity) 286 bbl |          |
| Other (Type)             |          |

**Berms**

| Type                                      | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |
|---|----------|---------------------|---------------------|-------------|--------|
| Metal                                     | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment: shares containment with PW tanks |          |                     |                     |             |        |
| Corrective Action:                        |          |                     |                     | Date:       |        |
| Contents                                  | #        | Capacity            | Type                | Tank ID     | SE GPS |
| PRODUCED WATER                            | 3        | OTHER               | STEEL AST           |             | ,      |
| Comment:                                  |          |                     |                     |             |        |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 286 bbl  |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Wells Served By Facilities Above**

|            |
|------------|
| API Number |
| 123-47580  |
| 123-47574  |
| 123-47573  |
| 123-47586  |
| 123-47585  |
| 123-47582  |
| 123-47569  |
| 123-47567  |

**AirsID**

|            |        |
|------------|--------|
| API Number | AirsID |
|------------|--------|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 456573 Type: WELL API Number: 123-47567 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 12/17/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 456578 Type: WELL API Number: 123-47569 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 02/25/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456583 Type: WELL API Number: 123-47573 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 12/17/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 456585 Type: WELL API Number: 123-47574 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/18/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 456588 Type: WELL API Number: 123-47577 Status: DG Insp. Status: ND

Facility ID: 456592 Type: WELL API Number: 123-47580 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/17/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 456594 Type: WELL API Number: 123-47582 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/16/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: PR

Corrective Action:

Date:

Facility ID: 456597 Type: WELL API Number: 123-47585 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 03/01/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 456599 Type: WELL API Number: 123-47586 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 11/16/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 6/10/2021 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: right;">Baja Berg 11-35HZ Pad at Location #456589 in Weld County Colorado.</p> <p>While there, I observed a Multi well pad and tank battery, PR at the time of inspection. During this inspection the following compliance issue was observed:</p> <p>430 Gas Meter Calibration: No card displayed to indicate calibration status, CA dat 7-10-2021.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | revasr | 06/10/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402715495    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5452786">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5452786</a> |
| 699303983    | location pics        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5452782">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5452782</a> |