

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2021

Submitted Date:

06/17/2021

Document Number:

701101608

FIELD INSPECTION FORM

Loc ID: 315155 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96155
Name of Operator: WHITING OIL & GAS CORPORATION
Address: 1700 LINCOLN STREET SUITE 4700
City: DENVER State: CO Zip: 80290

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
CO, Western	303-876-7091	whitingwesternco@whiting.com	Western slope inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230337	WELL	PR	10/01/2020	OW	103-07997	HILL 6-6	PR

General Comment:

COGCC Routine Inspection Report Summary
During this inspection the following compliance issues were observed:

- Oil in well cellar. Contacted Whiting Oil and Gas (Scott Swain) by phone Thursday 6/17/2021 and COGCC EPS (John Heil)
- Weeds around well, pump jack, location berms.
- Chemical secondary container at well is damaged.
- Location berm is damaged in northwest and northeast corners.
- Subsidence of ground at buried line marker.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around well, pump jack, location berms.		
Corrective Action:	Comply with Rule 606	Date:	06/26/2021

Overall Good:

Spills:

Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	Oil in well cellar.		
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.		Date: 06/18/2021

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230337 Type: WELL API Number: 103-07997 Status: PR Insp. Status: PR

Producing Well

Comment: [Pump jack in operation.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
				Material Handling And Spill Prevention	Fail	Chemical secondary container at well is damaged
Berms	Fail					Berm is damaged in two areas.
Compaction						

Comment: Chemical secondary container at well is damaged. Location berm is damaged in northwest and northeast corners. Subsidence of ground at buried line marker.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/03/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101610	Inspection 701101608 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457943