

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402707701

Date Received:  
06/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

SG Interests

inspection@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202529

Inspection Date: 03/31/2021

FIR Submit Date: 04/02/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 422990

Location Name: HL 11-89-19 Number: 1 County: \_\_\_\_\_

Qtrqtr: SENW Sec: 19 Twp: 11S Range: 89W Meridian: 6

Latitude: 39.088280 Longitude: -107.379530

FACILITY - API Number: 05-051- -00 Facility ID: 422990

Facility Name: HL 11-89-19 Number: 1

Qtrqtr: SENW Sec: 19 Twp: 11S Range: 89W Meridian: 6

Latitude: 39.088280 Longitude: -107.379530

CORRECTIVE ACTIONS:

1 CA# 147985

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.(2)C.

Date: 06/13/2020

Response: CA COMPLETED

Date of Completion: 06/02/2021

Operator  
Comment:

This Corrective action has several corrective actions within this one CA. This FIRR is being submitted for the slope drain inspection report stating it was not constructed with an appropriate outlet, nor properly secured. This same existing slope drain has been in place for 10 plus years and has had 10 plus inspections. Aside from adding a plug to the top of the drain, no changes have been made. Other inspections have never identified this slope drain as not being constructed using good engineering practices. However, SG added outlet projection upon receipt of this CA. Attached is the BMP design criteria SG uses for this slope drain. Please also note the design meets the definition per CDPHE:

The CDPHE defines good engineering in their COR 40000 Permit p. 21:

(9) Good Engineering, Hydrologic and Pollution Control Practices: are methods, procedures, and practices that:  
a. Are based on basic scientific fact(s). b. Reflect best industry practices and standards. c. Are appropriate for the conditions and pollutant sources. d. Provide appropriate solutions to meet the associated permit requirements, including practice based effluent limits.

COGCC Decision: **Not Approved**

COGCC Representative: COGCC Decision "Not Approved"; Inspection #696202826 on 6/15/2021 documented that stormwater corrective actions not have been addressed; corrective action remains applicable. In addition, the FIRR, Corrective action complete section, is not a forum for operators to disagree/argue with the corrective actions.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Eric Sanford

Signed:

Title: Land

Date: 6/16/2021 1:26:29 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402707701	FIR RESOLUTION SUBMITTED
402707765	BMP Stipulation

Total Attach: 2 Files