

Inspection Photos

6/15/2021

Operator: GUNNISON ENERGY LLC # 10515

Location ID: 324464

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 1: Photo shows equipment observed to be leaking, and where stained soils were documented in previous inspection. Photo shows stained soils have been removed.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 2: Continued from photo 1. Photo shows mechanical issues appear to remain an issue for the equipment, as additional fluids can be observed leaking at the base (arrow).

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 3: Photos 3-7 show various unused equipment or trash debris previously documented, have not been removed per the corrective actions.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 5: See comments under photo 3.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 6: See comments under photo 3.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 7: See comments under photo 3.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464




Photo 8: Previous inspection observed that the containment BMP at the tanks was inadequate. Photo shows that BMP appears to remain inadequate in accordance with Rule 603.o

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 10: Previous inspection observed that the containment BMP at the tanks was inadequate. Photo shows that BMP appears to remain inadequate in accordance with Rule 603.o

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 11: Photo shows areas on the northwest end of the Location have not been reclaimed in accordance with Rule 1003.b. Area observed being used to store equipment.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 12: Photo taken from the sediment trap on the southwest end of the Location. Previous inspections observed noxious weeds within the trap, as well as other areas of the Location. Photo shows Hoary cress also has established on Location.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 324464



Photo 13: Photo shows musk thistle rosette observed on the southern areas of the Location.



Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 14: Photo shows that neither a sediment pond/trap BMP has been installed, or reclamation conducted on the southern areas of the Location.