

Inspection Photos

API: 055-06190

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 1. Facing northwest toward the location. A road travels thru the center of the location. The cut slope of the location is visible along the right side of photo and run-on ditch shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 2. Facing west toward the location. A road travels thru the center of the location shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 3. Facing west along the fill slope of the location. The location consists predominately of noxious weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 4. Facing east along the fill slope of the location. The location consists predominately of noxious weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 5. View of noxious weeds observed at the location include: Cheat grass, Red stem filaree, Field bind weed, and Jointed Goat grass.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 6. View of Jointed goatgrass found on the location which is a List B noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 7. There appears to be pit liner at the surface at the southwest side of the pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 8. Facing east. The access road travels thru the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021

Inspection Photos



Photo 9. Facing northeast toward the location. The cut slope of the location is visible along the center of photo and run-on ditch shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/16/2021