

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/27/2021

Submitted Date:

06/02/2021

Document Number:

692403447

**FIELD INSPECTION FORM**

Loc ID 428533 Inspector Name: Colby, Lou On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
2 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10524  
 Name of Operator: GRMR OIL & GAS LLC  
 Address: P.O. BOX 6280  
 City: BROOMFIELD State: CO Zip: 80021

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		stubridy@jklmenergy.com	
	970-824-6827	John.Leone@gmroilandgas.com	
		jharrick@jklmenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428532	WELL	PA	09/08/2016	OW	081-07720	North Castor Gulch 1-16	RI
430690	WELL	AL	12/07/2015	LO	081-07760	North Castor Gulch 4-16	RI
430691	WELL	AL	07/07/2016	LO	081-07761	North Castor Gulch 2-16	RI
430692	WELL	AL	12/07/2015	LO	081-07762	North Castor Gulch 3-16	RI
430693	WELL	AL	12/07/2015	LO	081-07763	North Castor Gulch 5-16	RI
430908	WELL	AL	12/07/2015	LO	081-07770	North Castor Gulch 9-16	RI
430909	WELL	AL	12/07/2015	LO	081-07771	North Castor Gulch 8-16	RI
430910	WELL	PA	09/11/2016	SI	081-07772	North Castor Gulch 6-16	RI
430911	WELL	AL	12/07/2015	LO	081-07773	North Castor Gulch 7-16	RI

**General Comment:**

This is a Final Reclamation Inspection, a Followup to Insp Doc#674104454 Dated 5/25/18 for two PA Wells, API#s 081-07720 & 081-07772 and an Abandoned Location Inspection, for Seven Wells, listed in Inspected Facilities above.

**Inspected Facilities**Facility ID: 428532 Type: WELL API Number: 081-07720 Status: PA Insp. Status: RIFacility ID: 430690 Type: WELL API Number: 081-07760 Status: AL Insp. Status: RIFacility ID: 430691 Type: WELL API Number: 081-07761 Status: AL Insp. Status: RIFacility ID: 430692 Type: WELL API Number: 081-07762 Status: AL Insp. Status: RIFacility ID: 430693 Type: WELL API Number: 081-07763 Status: AL Insp. Status: RIFacility ID: 430908 Type: WELL API Number: 081-07770 Status: AL Insp. Status: RIFacility ID: 430909 Type: WELL API Number: 081-07771 Status: AL Insp. Status: RIFacility ID: 430910 Type: WELL API Number: 081-07772 Status: PA Insp. Status: RIFacility ID: 430911 Type: WELL API Number: 081-07773 Status: AL Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed **Fail**

Gravel removed **Fail**

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass

Compaction alleviation Pass Dust and erosion control Pass

Non cropland: Revegetated 80% In Cropland: perennial forage \_\_\_\_\_

Weeds present Pass Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

CAs to control Weeds and address erosion have been resolved, ongoing weed control program is in place. Location Vegetation is well established and diverse.

CA to reclaim Access Road has Not been completed. Road is approx. 1.5 miles long running through private and state land. There are areas of steep cut and gradient. Refer to Photo log attached.

Operator had discussed submitting Variance Request after 2018 Inspection. FIRR Doc#401694150 date: 7/5/18 Operator response was "1) In the process of gathering information and documentation to request a reclamation variance for the access road only." No other submittals have been received related to a Variance Request for this Location. Location remains out of Compliance.

Corrective Action: **CA#1) Perform Final Reclamation of Access Road per COGCC 1004 Rules; all Reclamation Activities to be complete by November 1, 2018.**

Date **11/01/2018**

Overall Final Reclamation **Fail** Well Release on Active Location  Multi-Well Location

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402716288	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453621">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453621</a>
692403475	Inspection Photos RI	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453585">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453585</a>