

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/10/2021

Submitted Date:

06/11/2021

Document Number:

693700804

FIELD INSPECTION FORM
 Loc ID 323578 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Axelson, John		john.axelson@state.co.us	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245427	WELL	PR	10/01/2018	OW	123-13222	LONGMONT FARMS UNIT 5	EI
479267	SPILL OR RELEASE	AC	01/29/2021		-	Longmont Farms Unit #5 Flowline	EI

General Comment:

COGCC Inspection of Spill ID 479267 and followup to Field Inspection Report 693700789

Inspected Facilities									
Facility ID:	245427	Type:	WELL	API Number:	123-13222	Status:	PR	Insp. Status:	EI
Facility ID:	479267	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment:	Operator has prepared a bermed/lined area for sotckpiling oily waste pending trucks for disposal. Area appears adequate for temporary storage			
Corrective Action				Date:

Spill/Remediation:

Comment:	Operator continues to excavate flowline release. Current excavation is approximately 45'L x 30'W x 20'-25'D with possibly ~2000 cubic yards removed. No groundwater is present. Excavation has expanded north and south along flowline. Operator has staged approximately 500+ cubic yards of clean overburden from benched area onsite. Operator has created a lined/bermed area for temporary stockpile of oily waste. Operator is directed to Rule 915.e. and the Rule 915.e.(2) Soil Sampling and Analysis Guidance Document for guidance.			
Corrective Action:	Operator to submit Form 27 with Site Investigation and Remediation Workplan for remediation of this Spill (this was due by April 19, 2021). Form 27 should include proposed schedule for remediation activity, as well as proposed sampling and analysis plan for Spill characterization and remediation, confirmation of clean overburden, and confirmation of oily waste stockpile area. Operator also to submit Form 19 Supplemental Report with root cause and corrective action for flowline failure and resolution of Spill via Work proceeding under a Form 27. Operator to submit results of flowline repair pressure test on Form 19 Supplemental Report.			Date: 04/28/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402715823	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453043
693700810	LongmontFarmsUnit5Spill Photos6-10-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453039