

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/10/2021

Submitted Date:

06/11/2021

Document Number:

693700806

FIELD INSPECTION FORM

Loc ID 318500 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Axelson, John		john.axelson@state.co.us	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241419	WELL	PR	11/01/2020	OW	123-09208	WOOLLEY 2	EI
479484	SPILL OR RELEASE	AC	05/19/2021		-	Woolley#1	EI

General Comment:

COGCC inspection of Spill ID 479484 on the Woolley 1 flowline, followup to Field Inspection Report #693700788. Excavation has been backfilled.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Small drip/oily waste at rear of AST

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/11/2021

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		40.100933,-104.983330
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		
Comment: Earthen berm remains in eroded condition; corrective action date has lapsed				
Corrective Action: Repair secondary containment berm around produced water vessel;				Date: <u>05/28/2021</u>

Venting:

Yes/No


Comment:

Corrective Action:

Date:

Flaring:

Type <input type="text"/>	
Comment: <input type="text"/>	
Corrective Action: <input type="text"/>	Date: <input type="text"/>



Inspected Facilities

Facility ID: 241419 Type: WELL API Number: 123-09208 Status: PR Insp. Status: EI

Facility ID: 479484 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [COGCC Inspection of Woolley 1 flowline release. Excavation has been backfilled and material stockpile removed. Operator has submitted Form 19 Supplemental#402701211 for closure of Spill, form is under review by COGCC. COGCC will respond to Form 19 separate from this Field Inspection Report.](#)

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402715826	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453045
693700809	Woolley1Photos6-10-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453041