

Form 19 Information:

Site Name: Green #2

Date of Incident: 6/17/21

API #/Facility #: 05-001-08804 /203295

Legal Description: NWNW Sec. 18, T1S, R67W

Latitude/Longitude: 39.970309/-104.938092

AFE #: RC#: NA

Remediation # 18310

Within Municipality? no

Distance to Wetlands 0.5 miles northwest to nearest wetland

<https://www.fws.gov/wetlands/data/mapper.html>

Landuse: Agricultural

Surface water within one mile? 4105 feet northeast to un-named pond, 3151 feet northeast to un-named pond, 2466 feet east to Signal Ditch, 3833 feet southwest to Wadley Reservoir 3, 4907 feet southwest to Wadley Reservoir 2, 3101 southwest to Wadley Reservoir 1, 2900 feet northwest to German Ditch

Cause of failure and specific equipment? Historical release from wellhead; no obvious sign of equipment failure

Type of fluid released: condensate

Amount of Fluid released: unknown

Extent of excavation: 12'x15'x8' deep

Soil type: Silty Clay

Within one mile?

- **Livestock?** None observed
- **Occupied building?** 633 feet west to housing development, 2462 feet south to housing development, 3605 feet north to nearest occupied building, 4619 feet east to nearest occupied building

Groundwater encountered? No

- **DTW?** NA
- **Color?** NA
- **Odor?** NA
- **Sheen?** NA

Weather conditions at time of visit? 100°F and sunny

Number of wells within ½ mile (from DWR): 45 wells

Direction/distance to nearest water well: 875 northwest to nearest well (domestic)

Estimated Depth to Water: 980 feet

Impacted Soil Removed? Volume? Landfill? No impacted soil was removed