

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2021

Submitted Date:

06/21/2021

Document Number:

690102517

FIELD INSPECTION FORMLoc ID 323639 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspections@gwogco.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245511	WELL	TA	10/01/2019	OW	123-13306	KIELIAN 2-2	PA

General Comment:

COGCC Engineering Integrity Inspection; Flowline Removal Confirmation

Inspected Facilities

Facility ID: 245511 Type: WELL API Number: 123-13306 Status: TA Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Kielian 2-2) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402700373 received on 05/25/2021. COGCC form 42 notice of flowline pre-abandonment notice Doc #402671390 received 04/26/2021. All flowlines (OLF wellhead, dump and process) have been removed (confirmed via communications with GWOC and inspection); No flowline risers were observed at the (PA) wellhead or facility/ battery areas during this field inspection. Gas meter run (valves LOTO) is located on the N side of location.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #402710869 received on 06/17/2021: Potential impacts to soil and groundwater were observed at the wellhead during cut and cap activities. The exact cause of the release is unknown.	maclarej	06/21/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102520	Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459823
690102521	View of facility/ battery; Flowlines & Equip removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459824
690102522	View of (PA) wellhead; Flowlines (OLF) removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459825