

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2021

Submitted Date:

06/21/2021

Document Number:

690102519

FIELD INSPECTION FORM

Loc ID 333033 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@gwogco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287398	WELL	PA	07/23/2020	OW	123-24312	GREAT WESTERN 27-13	PA
287400	WELL	SI	04/01/2019	OW	123-24313	GREAT WESTERN 27-14	PA
287402	WELL	PA	05/28/2016	OW	123-24314	GREAT WESTERN 27-23	PA
287403	WELL	PA	07/23/2020	OW	123-24315	GREAT WESTERN 27-24	PA
287404	WELL	PA	07/23/2020	OW	123-24316	GREAT WESTERN 27-53	PA

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Removal Confirmation Photos uploaded](#)

Inspected Facilities

Facility ID: 287398 Type: WELL API Number: 123-24312 Status: PA Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Wells (GW 27-13, 27-14, 27-23, 27-24, 27-53) are plugged and abandoned; COGCC form 42 notice of start of plugging operations were received 7/ 2020 & 2/2021. Associated flowlines (on location wellhead, dump and process) have been removed (confirmed via communications and inspection); No flowline risers observed at the (PA) wellhead or facility/ battery (decommissioned/ tanks and equipment removed) areas during this field inspection. (1) gas gathering riser (midstream) is located on the W side of location.

Corrective Action: _____

Date: _____

Facility ID: 287400 Type: WELL API Number: 123-24313 Status: SI Insp. Status: PA

Facility ID: 287402 Type: WELL API Number: 123-24314 Status: PA Insp. Status: PA

Facility ID: 287403 Type: WELL API Number: 123-24315 Status: PA Insp. Status: PA

Facility ID: 287404 Type: WELL API Number: 123-24316 Status: PA Insp. Status: PA

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102527	View of location to S	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5460236
690102528	View of location to W; Gas gathering riser	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5460237