

Inspection Photos

Operator: Kinder Morgan
API: 083-06730
Date: 6/17/2021



Photo 1. View the project area facing center from the southwestern corner of the working area facing center.



Photo 2. View of cellar that is approximately 6-feet deep observed on the well pad. This needs to be covered or wildlife escape ramp installed.



Photo 3. View of the western project area from the southwestern corner of the working area, facing northward. Revegetation is progressing with western wheatgrass, alfalfa, smooth brome, and locoweed.



Photo 4. View of the southern project area from the southwestern corner facing eastward.



Photo 5. View of signed topsoil within the southwestern project area. Additional topsoil storage observed within the eastern project area.



Photo 6. View of reference area comprised of dryland cultivated field appears to be prepped for seeding.