

Inspection Photos
Operator: Seeley Operating
API: 083-06542
Date: 6/17/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with Indian ricegrass, cliffrose, rubber rabbitbrush, squirreltail, and young pinyon and juniper trees.



Photo 3. View of the eastern project area from the northeastern corner facing northward.



Photo 4. View of the northwestern berm at the well pad entrance.



Photo 5. View of the southern project area from the southwestern corner facing eastward.



Photo 6. Another view of the southern project area. Young pinyon tree established beneath dead tree here.



Photo 7. View of reference area comprised of pinyon and juniper woodland mixed with prickly pear, snakeweed, and squirreltail.