

Inspection Photos
Operator: Catamount
API: 067-09024
Date: 5/19/2021



Photo 1. View of project area from well pad southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with grasses such as wetern wheatgrass, sand dropseed, and intermediate wheatgrass.



Photos 3/4. View of musk thistles (approx 25 untreated; right photo) and 200 Russian knapweeds (left photo) observed within the project area.



Photo 5. View of reference area comprised of sagebrush shrubland with understory of grasses and forbs such as western wheatgrass, squirreltail, and mat penstemon.