

Inspection Photos
Location Name: Champlin 485 Amoco #1
Location ID: 320071



Photo 1 loc pic



Photo 2 WH no sign

Inspection Photos
Location Name: Champlin 485 Amoco #1
Location ID: 320071



Colorado Oil and Gas Conservation Commission
39.92989, -104.15258, 1464.9m
Jun 21, 2021 13:54:43

**Photo 3 Electric equipment in disrepair not able to operate.
Weeds on well site**



Colorado Oil and Gas Conservation Commission
39.92852, -104.15093, 1480.6m
Jun 21, 2021 14:04:13

Photo 4 facility pic

Inspection Photos
Location Name: Champlin 485 Amoco #1
Location ID: 320071



Photo 5 Produced water tank.



Photo 6 tank battery sign.

Inspection Photos
Location Name: Champlin 485 Amoco #1
Location ID: 320071



Photo 7 Crude oil tanks



Photo 8 Produced water tank NFPA placard faded need to be replaced.

Inspection Photos
Location Name: Champlin 485 Amoco #1
Location ID: 320071



Photo 9 facility pit



Photo 10 facility pit

Inspection Photos
Location Name: Champlin 485 Amoco #1
Location ID: 320071



Photo 11 no BMP in place to prevent pit berm sediment from leaving location.



Photo 12 pit berm sediment running into drainage.

Inspection Photos
Location Name: Champlin 485 Amoco #1
Location ID: 320071



Photo 13 photo of ditch on back side of facility. It appears to a dump site.



Photo 14 pit photo.

Inspection Photos
Location Name: Champlin 485 Amoco #1
Location ID: 320071



Photo 15 Large reels on pit berm.



Photo 16 large reels on pit berm.

Inspection Photos

Location Name: Champlin 485 Amoco #1

Location ID: 320071



Photo 17 gauge hatch open on crude oil tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources