

# Inspection Photos

6/21/2021

Operator: UTAH GAS OP LTD DBA UTAH GAS  
CORP - 10539

Location ID: 323915  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323915



**Photo 1:** Photo taken from the north end of the Location, facing east. Photos 1-4 provide an overview of the Location from east, southeast, southwest to west.

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323915



**Photo 2:** See comments under photo 1.



Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323915



**Photo 3:** See comments under photo 1.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323915



20210621

**Photo 4:** See comments under photo 1.



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323915



**Photo 5:** Photo taken from the east end of the Location, facing east. Photo shows areas where stormwater runoff concentrates and discharges from the pad.



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323915



**Photo 6:** Continued from photo 5. Photo shows erosion degradation (gully formation) observed on the slopes of the Location. Stormwater and erosion control measures to protect/stabilize slope, and to allow for proper stormwater discharge are missing or insufficient.



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323915



**Photo 7:** Photo taken from the west end of the Location, facing north. Photo shows example of uniform vegetative establishment observed on the interim areas.